










# COMPARISON OF DIRECT PART MARKING SOLUTION

## GRAVOTECH SOLUTIONS

## OTHER SOLUTIONS

		GRAVOTECH SOLUTIONS			OTHER SOLUTIONS						
		Laser	Dot-peen		Scribing	Label	Inkjet	Stamp marking	Electro-chemical	Engraving pen	
			Pneumatic	Electromagnetic							
<b>Result</b>											
<b>MARKING</b>	<b>Speed</b>	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	
	<b>Depth</b>	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	
	<b>Proofreading</b>	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	
	<b>Durability</b>	Service life of the part				Easy to tear off / degrade		Service life of the part			
	<b>Contrast</b>	✓	✗	✗	✗	✓	✓	✗	✓	✗	
	<b>Paint (after marking)</b>	✗	✓	✓	✓	✗	✗	✓	✗	✗	
<b>MACHINE</b>	<b>Production rate</b>	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	
	<b>Sound level</b>	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	●●●●●	
	<b>Consumables</b>	✗	✗	✗	✗	✓	✓	✗	✓	✗	

Do you need more information?

[Contact a Gravotech expert](#)

